

Hawkeye Industries Inc.



TROUBLE SHOOTING GUIDE



Duratec® Thinner

Duratec Thinner (39 LAC-1)

Problem	Cause	Solution
Failure to rapidly mix into Duratec products	Cold thinner	Warm thinner and/or Duratec products Continue to machine mix until blended with Duratec products

[Home Page](#) [Product Line Card](#)
[Contents/Trouble Shooting Guide](#)



Hawkeye Industries Inc.

P O Box 415 Bloomington, CA 92316

Tel 909-546-1160; Toll Free 800-977-0060; Fax: 909-546-1161

Email productinfo@duratec1.com Web www.duratec1.com

Revised 3-07-06