

Hawkeye Industries Inc.



# TROUBLE SHOOTING GUIDE



Duratec® Vinyl Ester Fairing Putty

## Duratec Vinyl Ester Fairing Putty (1810-013 Untinted)

| <b>Problem</b>          | <b>Cause</b>                  | <b>Solution</b>                                      |
|-------------------------|-------------------------------|--|
| Putty gels too quickly. | Ambient temperature too warm. | Cool putty prior to catalyzing.                      |
| Putty under cured       | Ambient temperature too cold. | Apply in 65°F, 18°C or warmer temperatures.          |
| Putty not cured         | Too little catalyst used.     | Catalyze with 2 percent full strength mekP catalyst. |

[Home Page](#) [Product Line Card](#)

[Contents/Trouble Shooting Guide](#)



**Hawkeye Industries Inc.**

P O Box 415 Bloomington, CA 92316

Tel 909-546-1160; Toll Free 800-977-0060; Fax: 909-546-1161

Email [productinfo@duratec1.com](mailto:productinfo@duratec1.com) Web [www.duratec1.com](http://www.duratec1.com)

Revised 3-07-06